



CREIGHTON SCHOOL DIVISION No. 111

Asbestos Registry

Type of Facility (e.g. healthcare, school, government building, crown building): School Buildings

Name of RHA, School District or Crown (if applicable): Creighton School Division No. 111

Owner Name (if applicable): _____

Location (Street address, City): 325 Main Street, Creighton, SK S0P 0A0

Facility Name (if applicable): Creighton Community School

Date of Submission: March 14, 2014

Contact Person: Bob Smith Title: Director of Education

Telephone: 306-688-5825 Email: bsmith@creightonschool.com

1. Type of Asbestos – Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (optional)
Ceiling cement board	Storage Room - #106	Non-friable 4x8 sheet	10 foot high ceiling Painted Board Limited Access	Label on Ceiling Board
Brick chimney insulation	Boiler Room - #105	Non-friable insulation	Locked Room - Painted Board over insulation Locked with restricted access	Label on Chimney



Saskatchewan Labour Occupational Health and Safety Division
 6th Floor, 1870 Albert Street
 REGINA SK S4P 3V7
 Work: 787-4507
 Toll Free: 1-800-567-7233
 Fax Number: 787-2208

**Occupational Health
 Officer Report**

Ref. No. **OR-DOR-0494**
 Employer File No. 956

Name of Employer Creighton School Division No 111
 Employer Address 325 Main St., CREIGHTON, SK S0P 0A0
 Place of Employment Creighton School Box 158, Main St., CREIGHTON, SK S0P 0A0
 Department/Work Area Creighton Community School

Date 05 August 2004
 Day Month Year

Dave Ogram
 Occupational Health Officer

Summary

The records of the Occupational Hygiene Unit, OH&S Division, Sask Labour indicate that at one time there was asbestos present at Creighton Community School. OH&S Division representatives are currently visiting as many as possible of the schools where asbestos was known to be present at one time.

The Saskatchewan Occupational Health and Safety Regulations 1996 state that asbestos containing materials must be identified, labeled and regularly inspected. The pertinent legislation is attached to this report.

On August 5, 2004 an inspection was conducted to evaluate potential asbestos in the school. Several areas where asbestos has been known to be present in schools were viewed, including the boiler room, industrial arts area, roof decking, and a few ceilings.

5 samples were taken and analyzed for the presence of asbestos. Results were as follows:

- Sample 1 - Stipple Material from Room 115----- No asbestos found
- Sample 2 - Chimney Insulation----- Chrysotile asbestos present
- Sample 3 - Elbow in Boiler Room on Hot Water Pipe-----No asbestos found
- Sample 4 - Ceiling Material in Boiler Room-----Chrysotile asbestos present
- Sample 5 - Floor Debris - 2nd Floor (Library Area)-----No asbestos found

Please respond in writing by November 15, 2004 to the OH&S Division (Attention: Dave Ogram) and provide the following information:

1. Indicate how asbestos-containing materials in the school will be labeled as per regulation 335.
2. Indicate how and where records are kept with respect to the annual inspection of any of these materials that could release airborne asbestos if damaged as per regulation 336
3. Who is the person responsible for the record keeping mentioned above?

The attached OH&S Regulations apply to all schools in your Division. The selection of the Creighton Community School was based on our records and does not imply that any other schools in your Division do not have asbestos containing materials. As well this inspection was not an all inclusive evaluation of asbestos containing materials in the school. When suspect surfaces are uncovered, the material must be evaluated prior to disturbing the material.

If you have any questions I can be contacted at one of the phone numbers in the header of this report. Ensure that a copy of this report is posted in the school for the information of all workers.

Report received on behalf of
the Employer

Austin Gerein
Name (print)

Superintendent of Schools
Position

Signature

Copy received on behalf of
the Occupational Health
Committee, Representative,
or Workers

Copies mailed to:

Guy Row, Principal
Employer Co-chair, OHC
Employee Co-chair, OHC
Employees (TO BE POSTED)

Signature of Employee Representative

Signature of Employer Representative

cc: Post for Information of Workers Occupational
Health Committee/Representative
Office